

cc: E.P. Barrett

Send Reply

Mr. BSA
Remington Arms
Rm. 31210

17210

DATE 12/10/51 ☐ URGENT
FILE NO. ☐ CLAIMED AS POSSIBLE
☐ NO REPLY NEEDED

ATTENTION

SUBJECT Rem 700 DL 633556 303CA

gun fires when the bolt is closed.
Witness repair and return.

SIGNED

Chas. E. Taylor

DATE OF REPLY

SIGNED

RECIPIENT: WRITE REPLY, RETURN WHITE TO SENDER. KEEP THIS PINK COPY.

Further examination revealed that the trigger assembly was full of solidified oil, to the extent the bolt stop lever was barely operable.

Based on our findings, Remington Arms Company, Inc., cannot accept any liability or responsibility for the reported malfunction. We can only assume that the oil accumulation, under certain circumstances, caused the accidental discharges. As stated in the Owner's Manual, the Model 700 trigger assembly is designed not to require any lubrication, and care should be taken to avoid oil getting into the mechanism.