

Doc: E.P. Barrett

GUN CITY U.S.A., INC.
573 Marlborough Road
NASHVILLE, TENNESSEE 37210

(615) 296-6127

DATE 12/14/77

☐ URGENT

FILE NO.

☐ CLERK IN POWER

☐ NO REPLY NEEDED

ATTENTION

SUBJECT Rem. 700 ADE #6225546 303CM

Customer says that gun fires when the bolt is closed.
Please repair and return.

SIGNED

DATE OF REPLY

SIGNED

RECIPIENT: WRITE REPLY. RETURN WHITE TO SENDER. KEEP THIS PINK COPY.

Further examination revealed that the trigger assembly was full of solidified oil, to the extent the bolt stop lever was barely operable.

Based on our findings, Remington Arms Company, Inc., cannot accept any liability or responsibility for the reported malfunction. We can only assume that the oil accumulation, under certain circumstances, caused the accidental discharges. As stated in the Owner's Manual, the Model 700 trigger assembly is designed not to require any lubrication, and care should be taken to avoid oil getting into the mechanism.