

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 92-24094

INITIAL CUSTOMER ORDER NO.

JIM

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/06/92	11/10/92		6333729		700 25-06 RDL
ACCESSORIES SCOPE BASE L/SIGHTS L/STUDS KT 5-70 2ND TIME 1					

FROM:

SHIP TO:

HONEYCUTT, B M
RT 1 BOX 681
FLOYD VA 24091

HONEYCUTT, B M
RT 1 BOX 681
FLOYD VA 24091

24091

CUST NO:069882 C.O.D.L

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED 11-25-92	VIA UPS
IN CONDITION					REPAIR CHARGE
☐ NEW					EXCISE
☐ LIGHTLY WORN					TAX
☐ WORN					INSURANCE
☒ VERY WORN					UPS
☐ UNREPAIRABLE					PARCEL POST
☐ MARRED	TOTAL				

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
W/CLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
SLT ASSY.		B3			E2	F2
REL ASSY.		B4		D1	E3	F3
EC. ASSY.		B5		D2	E4	F4
OOD			C1	D3	E5	F5
ETAL			C2			

IN FAULT *Cannot duplicate complaint. Rifle trigger assembly does not fire normally. Trigger assembly has been tested outside factory - trigger pull is 24 pounds, this is well below our maximum spec.*

Trigger pull 24 pounds; rear lift .008"

ITS	COMMENTS <i>Offer following options:</i>					
	1) to re-adjust present trigger assembly to factory specs					
	2) to install new trigger assembly at normal cost, as getting good-will, & that will better restore confidence in the rifle.					
	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
	DE					
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PPS 02383