

RECEIVING AND ESTIMATING REPORT

COMMENTS *To Product Service*  
 W/ TASCO 3 X 9 SCOPE & COVERS

ORDER  
 R 94-13148

INITIAL FJB	CUSTOMER ORDER NO.	DATE RECEIVED 04/14/94		DATE OPENED 04/15/94	DATE CODE DF 9-85	SERIAL NUMBER B6748091	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06	ADL
ACCESSORIES W/STUDS		SCOPE MNTS		SCOPE BASE		HARD CASE			
L/ REAR SIGHT									

FROM: HUBBARD, WARREN J  
 N 10606 CO RD 358  
 STEPHENSON MI 49858

SHIP TO: HUBBARD, WARREN J  
 N 10606 CO RD 358  
 STEPHENSON MI 49858

CUST NO 096013 C.D.D.L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	------------

GUN CONDITION <input type="checkbox"/> NEW <input type="checkbox"/> LIGHTLY WORN <input type="checkbox"/> WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> UNREPAIRABLE <input type="checkbox"/> MARRED	REPAIR CHARGE
	EXCISE
	TAX
	INSURANCE
	UPS
	PARCEL POST
	TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Could not inspect customer concern, however, observation indicated that the action and trigger mechanism are correct with a third spring under the action must be missing. This is the same condition the customer reported.*

PARTS *found one previous observation*

COMMENTS *Upper trigger mechanism clean action at 1/2 normal adjustment. Part was good at good will. Go ahead.*

REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

*Super*