

COMMENTS

ORDER
92-17862

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
08/26/92	09/04/92	DU 9-71	6478324		700 270 ADL
ACCESSORIES	W/STUDS	SCOPE BASE	L/SIGHTS		

FROM:

SHIP TO:

HURLEY, LARRY
PO BOX 932
CLINTON

TN 377179

HURLEY, LARRY
PO BOX 932
CLINTON

TN
37717

CUST NO: 065954 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

SUN CONDITION

☐ NEW
☐ LIGHTLY WORN
☐ WORN
☒ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PÄRCEL POST

TOTAL	100
---	---

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	<i>Left sometimes fires when safety is released also, sometimes when bolt is closed</i>					F1
BOLT ASSY.						F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT Cannot duplicate either of these complaints after many attempts. However, it was noted that rust is present on the bottom side of the trigger and on the connector. Also, the trigger operation is somewhat slow, possibly because of this rusted condition.

Trigger pull $3\frac{1}{2}$ pounds; ear-lift .013"

ARTS	COMMENTS	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTE
	Time trigger assembly is rusted from unknown cause. Trigger Trigger became of the age of the rifle, offer new trigger, considerably at trouble cost, as a gesture of good-	ML					
		GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/

PPS 02512