

# RECEIVING AND ESTIMATING REPORT

COMMENTS

W/LEUPOLD 3X9 SCOPE

INITIAL	CUSTOMER ORDER NO.		DATE RECEIVED		DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER
P.S.			4/22/91	04/24/91	PR 6-68		356899	700	30-06	R 91-09662
ACCESSORIES			W/STUDS		HARD CASE		SCOPE MNTS		SCOPE BASE	
					L/REAR SIGHT					

FROM:	SHIP TO:
KING, DAVID J BOX 594 KODIAK	KING, DAVID J BOX 594 KODIAK
AK 99615	AK 99615

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA <input checked="" type="checkbox"/> UPS
--------------	--------------------	--------------------------------	------------	------------	-----------	---

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	-----	-----------	-----	-------------	-------

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☒ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: "...at times fire sometimes, and other it fails to fire. After I pull the trigger, it will fire on a delayed period of time."

MAIN FAULT: Trigger assembly is contaminated with an oily, gummy residue. As received, the rear sight cam is sticking to the trigger assembly side plate. Rifle operates normally at room temperature, however, cold temperatures could cause the described problems.

RTS: Clean present trigger assembly, if possible, if not, send repair estimates for a replacement trigger assembly at  $\pm$  normal cost, as a gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	D. TE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PPS 02739