

## RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 94-01326

INITIAL CUSTOMER ORDER NO.

W/I SPENT CASE

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/10/94

01/11/94

FN 6-93

C680660B

700 30-06

ADL

ACCESSORIES

W/STUDS

FROM:

SHIP TO:

KIRBY RD GUN SHOP  
770 S KIRBY RD  
BLOOMINGTON

IN 47403

KIRBY RD GUN SHOP  
770 S KIRBY RD  
BLOOMINGTONIN  
47403

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

CUST NO: 043309 C.O.D.

PROM. DATE

ESTIMATED

VIA

063103

WRITE ☐

UPS

GUN CONDITION

- ☐ NEW  
☐ LIGHTLY WORN  
☐ WORN  
☐ VERY WORN  
☒ UNREPAIRABLE  
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

*\* 1/2 Retail**Hold for reply*

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

*Customer took gun home, fired it and the  
wood splintered and the trigger housing  
came out*

MAIN FAULT

*Mfg date 6/93 Gun was subjected to extreme high pressure.  
Bolt had to be unscrewed in order to remove breech bolt from  
Receiver. Examination of the incident casing confirms excessive  
pressure showing near head separation. The incident shell did  
not have a factory crimp on the neck. Origin/mfg of shell  
is not Remington Factory produced. However, as a strictly  
as a gesture of good will offer replacement rifle at*

PARTS

COMMENTS

*1/2 price**Remac #**Retain incident shell until  
resolved.*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/92