

Roops

Trigger pull $4 \frac{1}{2} \pm$

Sec. Lift .0105"

Persons will now discuss that

Heavy cycling on bottom of receiver and in/on
trigger assembly

Cannot duplicate complaint at this time
Open functions as designed.