

August 16, 1969

REC

AUG 22 1969

W.A. STECKL

R-89 A#33
Mr. J. A. Steckl

Product Service, Remington Arms Co. Inc.

Dear Mr. Steckl:

THANK you for your INTEREST IN LOOKING INTO my inquiry regarding the Remington 30-06 BOL which I forwarded for your INSPECTION.

The problem which I REPORTED was one of TWO. The first occurred some time ago when the Rifle fired while being lowered onto a target. Almost no pressure was placed on the Trigger when the rifle fired. The second incident was REPORTED to you when the rifle fired AFTER the Safety was Released AND the Trigger was NOT Touched at all.

BECAUSE of the TWO incidents I AM Concerned for reasons of safety, either for myself or for some OTHER user. BECAUSE of this I THINK IT would be in the BEST INTERESTS of all concerned to REPLACE the Trigger Assembly. Replacement would preclude ANY possibility of A REOCCURRENCE.

Again, I would like to THANK you for your interest.

Sincerely,
Joseph J. Murray