

RECEIVING AND ESTIMATING REPORT

COMMENTS

ATTN: J. STEKL

CUSTOMER ORDER NO.

RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
16/90	09/18/90	RZ 11-75	A6208763	600 243 MOHAWK	R 90-24056
SRIES SLING STRAP W/STUDS W/SWIVELS SCOPE BASE L/SIGHTS					
W/ RECOIL PAD					

SHIP TO:

FRIDGEN, LYNN
RT 6
BOX 6366
PALESTINE TX 75801

MAIL & MORE
712 W OAK ST

PALESTINE

TX
75801

ITEM NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
					UPS

CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☒ VERY WORN ☐ MISUSED ☒ MARRED

REPAIR REQUEST

... it discharged when I took it off safety...

ULT *Could not duplicate complaint, however, disassembly revealed
screw has been removed from all 3 trigger adjusting screws and
screws have been affixed outside of factory - 1) no trigger interaction
2) trigger over travel 3) excessive engagement*

*either re-adjust trigger assembly to
proper specification or, if that is not
possible, send quotation for & round
pin to replace trigger assembly.*

*9/21/90
J.S.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6/88