

AFTER LUBRICATING TRIGGER GROUP W/ REM OIL
AND WORKING THE ACTION - IT STARTED TO
WORK RIGHT.

I DID NOT TOUCH TRIGGER ADJUSTMENT SCREWS.
TRIGGER SEEMS A LITTLE HAIRY - NO CREEP, CLEAN BREAK