

RECEIVING AND ESTIMATING REPORT

INITIALS		CUSTOMER ORDER NO.		COMMENTS	
RCP				ATTN: JIM STEKL W/ 1 SPENT CASE	
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
08/14/90	08/22/90	AG 3-B6	B6778672	700 270 ADL	R 90-22374
ACCESSORIES		W/STUDS			
FROM			SHIP TO:		
SCHEUER, TOM 527 ELIZABETH ST MISHICOT WI 54228			SCHEUER, TOM 527 ELIZABETH ST MISHICOT WI 54228		
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	FROM DATE	ESTIMATED	VIA
					V 422012332
REPAIR CHARGE					
TAX					
INSURANCE					
UPS					
PARCEL POST					
TOTAL					
GUN CONDITION:					
☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED					
CUSTOMER'S REQUEST					
1) shell head failed - expanded primer pocket - Remington factory load 2) rpb agreed to have receiver headspace.					
MAIN FAULT					
Primer pocket of incident round expanded & dumped gas back into action.					
PARTS					
1) shell headspace of rpb & correct if necessary. 2) check foot for any damage to shroud. 3) Test rpb after any repairs. 4) Please expect 1st week, as rpb is needed for September hunt.					
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

REV. 6/88