

Remington

DATE 5/25/88 15

WAIT REPLY & CHECK

Remington

REMINGTON ARMS COMPANY, INC. OR R.O.

SPORTING FIREARMS, AMMUNITION, TARGETS AND TRAPS


PLEASE MAIL
REMITTANCE
TO BOX CHECKED

BRIDGEPORT, CONN. 06602

X UNION, N. Y. 13357

INVOICE NO R-88-12950

INVOICE DATE

SOLD
TOVictor E. Spear
R.R. #2
Box 61
Churubusco IN 46723

OUR ORDER NO R-88-12950-700

OUR ORDER NO

SHIP: VIA UPS

Ad 3-72

700 243 6539015
L/wood, scope base, L/sight on rear rampCOMPLAINT: Almost every time bolt is let down it fires-also
fires when safety is released.MAIN FAULT: Trigger has been grossly misadjusted outside
factory. Trigger pull 1 pound, rear engagement so misadjusted,
rifle will not cock most of the time.

1. 26345 Trigger assem. R.O.C.
2. Polished chamber
3. Check heading

TOTAL REPAIR CHARGE	35.00
TAX 55	1.75
PARCEL POST CPS	3.44
TOTAL CHARGES	40.19

40.19

THE ITEM ABOVE HAS BEEN RECEIVED AND IS BEING REPAIRED.
REPAIRS WILL BE MADE WITHIN 4-6 WEEKS.
THE CUSTOMER WILL BE NOTIFIED BY MAIL WHEN THE ITEM IS READY FOR PICKUP.
THE CUSTOMER WILL BE RESPONSIBLE FOR THE FREIGHT TO THE PLACE OF PICKUP.

REPAIRS WILL BE MADE WITHIN 4-6 WEEKS.
THE CUSTOMER WILL BE NOTIFIED BY MAIL WHEN THE ITEM IS READY FOR PICKUP.
THE CUSTOMER WILL BE RESPONSIBLE FOR THE FREIGHT TO THE PLACE OF PICKUP.

CUSTOMERS SIGNATURE