

Remington Arms Co., Inc.

Product Service

Legal Case #:10847

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
455135	8/5/2014	10/30/2014	10/31/2014				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Gregory	Florucci	51 Hovey Rd.	Woodbury	VT	05681		H 802-476-1955 C 802-472-5770

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Hit wall outside of home	Cause:4038	Could Not Duplicate Concern	
S	Unexpected discharge	Concern:1023	Delayed Firing - Firearms	Unknown
C				

Service Request# 131034 - Notes on repair - "7/31/14: Customer stated the gun discharged unexpectedly, the bullet bounced off concrete & hit the wall outside his home". df 10/31/14: I spoke w/customer by phone. He stated he loaded the gun, closed the bolt, nothing happened but as he was walking down his driveway holding the gun downward, it fired. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/300 BLK OU	84205	RR76311C	WH	8/28/2013 11:02:43 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	WAL-MART STORE 2682		U			

CONCERN:UNEXPECTED DISCHARGE

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - -						
Repair at n/c						
under recall						

Repair/Replacement Repair/Replacement
 Cost Date
 \$27

10/31/14: Per Ilion - Could not duplicate concern. TRIGGER ASSEMBLY WAS UPDATED BEFORE RECEIVED FOR P.S. EXAM. I emailed Ilion to check over completely, make sure trigger is back within specs or replace at no charge if necessary. If possible, please send for gallery testing. Notes on the repair state the customer sent gun in with a muzzle brake. df


Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		K.COFFIN
	Exam Date		10/30/2014
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	TRIGGER ASSEMBLY WAS UPDATED BEFORE RECEIVED FOR P.S. EXAM.
Barrel	Description		16" 300BLKOUT
	Date Code		WH
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	

	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		XMP
	Function	Like new; Functioning	
Sear	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	3.5#
	Altered	False	SEALANT PRESENT
	Sub-Assembly	X-Mark Pro	

RR76311C

Model: 700



RE00455135

10847

