

Date: 2/08/05

By: Bruce Travis Sr.

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Bruce J. Mount

R.E. Number: 92217

Reason for inspection: FSR

FIREARM

Manufacturer: Rem. Model: 700

Serial Number: 6540941 Date of Manufacture: 3/72

Overall external condition: Good

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: ALTERED

Adjustments/alterations: ALTERED

Other: SLUGGISH/STICKY part movement

Headspace: —

Function evaluation:

Feeding: _____

Extraction/ejection: _____

Trigger pull: 5#

Manual safety: OKAY - BOLT LOCK

Test firing results (if applicable): _____

DISPOSITION

could not duplicate concern. Trig. set screws altered +
Trig. works sluggish/sticks from dried lubrication residue.
Replace TPA clean + checkover for cost of Bolt Lock
Program \$20.00
Quote

ADDITIONAL COMMENTS