

RECEIVING AND ESTIMATING REPORT

CUST NO: 002719 WILM

COMMENTS

L/ BLACK TIP ON STOCK

AL CUSTOMER ORDER NO.

B 90859

RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

MODEL AND GRADE

ORDER

/28/91

08/29/91

KZ 5-75

6854937

700 25-06

R 91-17097

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

DM:

AHLMANS
ROUTE 1 BOX 20
MORRISTOWN
USA

MN 55052

SHIP TO:

AHLMANS
ROUTE 1 BOX 20
MORRISTOWN
USA

MN 55052

NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

9-16-91

UPS

AIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

Discharges when bolt is closed.

FAULT

Could not duplicate complaint. However, disassembly of rifle revealed upper assembly has been improperly adjusted out of factory - 1) trigger all below spec at 2 pounds; 2) insufficient over travel. Limited of rifle is loaded with dirt and dust also. Improper maintenance

Send repair quotation for cleaning and new trigger assembly (1 round cost, as good-will gesture)

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/90

PS00361

90854

TO: Rev.

This firearm has the following defect: discharges

when bolt is closed

Please repair under warranty at no charge and return directly to us. If not covered by warranty, please send repair estimate before proceeding. Thank you.

AHLMAN'S INC. Rt. 1, Box 20, Morristown, MN 55052

FIXING AND ESTIMATING REPORT

COMMENTS

L/ BLACK TIP ON STOCK

SERIAL NUMBER

6854937

MODEL AND GRADE

700 25-06

R

BASE

L/SIGHTS

SHIP TO:

AHLMANS
ROUTE 1 BOX 20
MORRISTOWN
USA

550

MN 55052

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

9-16-91

VIA

INSURANCE

UPS

PARCEL POST

TOTAL

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ M

REPAIR REQUEST

charges when bolt is closed.

Could not duplicate complaint. However, disassembly of rifle assembly has been inspected and found out of spec. - 1) blow spec. at 200 yds, 2) insufficient over travel. Rifle is loaded with dust and dirt also. Improper maintenance.

Send repair quotation for clean and new trigger assembly (1/2 cost, as good-will gesture)

REPAIRMAN

DE

PROOF

CLEAN

TEST

TARGET

GALLERY TESTER

DATE

DATE

DATE

DATE

OFFICE COPY

PS00363

RECEIVING AND ESTIMATING REPORT

COMMENTS

CUST NO: 002719 WILM

L/ BLACK TIP ON STOCK

INITIAL CUSTOMER ORDER NO.

FJB 90059

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

MODEL AND GRADE

08/28/91

08/29/91

KZ 5-75

6854937

700 25-06

ORDER

R 91-17097

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

AHLMANS
ROUTE 1 BOX 20
MORRISTOWN
USA

MN 55052

SHIP TO:

AHLMANS
ROUTE 1 BOX 20
MORRISTOWN
USA

MN
55052

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

9-16-91

UPS

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☒ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

Discharges when bolt is closed.

MAIN FAULT

Could not duplicate complaint. However, disassembly of rifle revealed trigger assembly has been improperly adjusted out of factory - 1) trigger pull below spec. at 2 pounds 2) insufficient over travel. Disassembly of rifle is loaded with dirt and dust etc. Improper maintenance

PARTS:

Send repair quotation for cleaning and new trigger assembly (to normal cost as good-will gesture)

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

RD6925 REV. 7/90

PS00364