

**FEDERAL LAW ENFORCEMENT TRAINING CENTER  
WEAPONS REPAIR FACILITY  
BUILDING 221**

## WORK ORDER REQUEST

ORIGINATING OFFICE:	REQUESTED BY:	BLDG/ROOM NO:	EXT:	DATE OF REQUEST:
Albemarle P.D. NC	Jeff Crisco	PROP Class	803	1/16/98
NUMBER OF WEAPONS(s):	MAKE/TYPE:	SERIAL NO(s):		
	Rem 700P	D6812946		

*M. K. Koda*

**DESCRIPTION OF WORK REQUESTED:**

SLAM FIRE occurs & Rifle fails to Cock each time

**APPROVAL OF: Chief, Firearms Division.**
Name: *B. J. Smith*Date: 1/16/98☒ Yes ☐ No

Reason for Disapproval: \_\_\_\_\_

### ACTION

WEAPON(s) IN: 1/16/98

(Date)

ACCEPTED BY: \_\_\_\_\_

(Below Factory Spec) Name/Title

DISPOSITION: Upon intake trigger poundage was 1.7 lbs. with almost no  
sear engagement. Trigger mech screw seal was disturbed.

Detailed Clean/Lube Bolt.

Trigger won't Properly set for Sear Engagement —

Return to Factory.

WORK PERFORMED BY: *James Brumley*WORK HOURS INVOLVED: 3 1/4 HR.WEAPON(s) OUT: 1-16-98

(Date)

RECEIVED BY: *Jeff A. Crisco*

(Name/Title)

**FIREARMS LISTING**  
(See Reverse)