

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700
Madison, NC 27025-0700

Parts/Repairs
Fax

800-243-9700
336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00088573 Account # - R-	Description/Serial Number ML068505 REPLACEMENT ML250519 Model 700ML Center Fire Caliber: 54	Date Received - 11/30/2004 Estimate Date - Current Date - 12/2/2004
Customer CLINT ALSBURY 149 S VAN BURREN ST CHERRY VALLEY, IL 61016 US	Return To CLINT ALSBURY 149 S VAN BURREN ST CHERRY VALLEY, IL 61016 US	
Phone (H) (815)-332-4224 Phone (W)	Fax Email	

Problems			
Reported		Found	
M101	ACCURACY	M101	ACCURACY
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FO
M993	FIRES WHEN RELEASING SAFETY		

Technician's Comments	
Condition	CUSTOMER WANTS ORIGINAL BOX BACK
Problem/Notes	Could not duplicate concern. Found trigger pin rusty and trigger sluggish. Repair as needed and replace trigger assm. comp. Arm mfg. 1997 bore is rough and dirty.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F107448	700 ML SS BBL ASSB 26" .45 Cal.	1	Y
F99294	700 ML SS TRIG ASSB	1	Y
Part	Total:	2	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	1	Y
Service	Total:	1	