

Repair Order Number



<b>Repair Order Number</b> RE00060392	<b>Description/Serial Number</b> A6167250	<b>Repairman -</b> Richard Hilts
<b>Account # - R-</b>	<b>Model 788 Center Fire Caliber: 308</b>	<b>Date Received -</b> 1/24/2003
	<b>L/CLIP</b>	<b>Estimate Date -</b>
		<b>Current Date -</b> 1/30/2003
<b>Customer</b> LOUIS AMADIO 121 S EASTVIEW AVE FEASTERVILLE, PA 19052 US		<b>Return To</b> LOUIS AMADIO 121 S EASTVIEW AVE FEASTERVILLE, PA 19052 US
<b>Phone (H)</b> (215)-322-6854 XHOM	<b>Fax</b>	
<b>Phone (W)</b> (215)-443-1120 XWRK	<b>Email</b> Louis.Amadio@willowgr	

Reported		Problems Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M106	COULD NOT DUPLICATE CUSTOMER

Repair		Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
<b>Material #</b>	<b>MaterialDesc</b>				
<b>Service</b>					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000118	GR-CLEAN	1	1	0	Y
4000119	GR-TEST	1	1	0	Y
4000294	GR-CHECK TPA	1	1	0	Y
<b>Service Total:</b>		<b>3</b>	<b>3</b>	<b>0</b>	

<b>ProblemNotes</b>	Safety plunger spring slightly weak, replaced, and the trigger and inside of trigger housing were dirty and coated with a heavy/ thick/sticky substance. As a gesture of good-will, cleaned and checked over, appears to be ok.				
<b>Repairman</b>	<b>Proof</b>	<b>Clean</b>	<b>Test</b>	<b>Target</b>	<b>Pattern</b>
Gallery Tester	Date	Date	Date	Date	Date