

Supry, Fred L.

To: Foster, Greg
Subject: Repair 78127

Greg,

As received we were unable to duplicate the FSR concern. When we disassembled the trigger assembly we found some rust between the trigger pin and the trigger pin hole in the trigger. The trigger assembly was also extremely oily. It appears that the unit was being flooded with oil, rather than being cleaned on only lightly oiled as we recommend.

We forwarded the rifle to Arms Service to have a new trigger assembly installed. This work is being done at n/c to the department as a gesture of goodwill.

Fred Supry
Product Service Manager
AFTE Technical Advisor
Remington Arms Company
14 Hoefler Avenue
Ilion, NY 13357

Office: 315-895-3606
Fax: 315-895-3661

fred.supry@remington.com