## ngton.

Repair Form

(NOTE: Please print and complete this for	orm, and then include it with your firearm.)

(NOTE: Please print and complete this form, and then include it with your firearm.)		
Model Number: 700 270 Win	Serial Number: 10394/	
Name: Charles Anselmo	Date of Purchase: Summer 1964	
Address (no PO Boxes): 322 Marion		
City: Sandpoint	State: Idaho Zip: 83864	
Phone (Daytime): 208-267-939/	Fax: 208-267-838/	
E-mail Address: kia cea a nidlink. com		
Please describe your problem: Rifle is sent subject to		
manufacturer recall to replace, both -lock,		
mechanism. Rifle was not used for several years		
until recently, Friends	used rifle and it discharge	
once when bott has	closed. This also occurred	
when I worked the	bolt while rifle was empty.	
Additional Information (Ammo tune brand boulded as if a significant		

nation: (Ammo type, brand, handload specifications, etc.)

NOTE: Prior to shipping your firearm, contact the Repair S provided and estimated repair time.

WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

- :: Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
- Remove all accessories from your firearm to prevent loss or damage.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

,03941

RE00061559

Could not duplicate

trigger pull of bolt release

sluggish. Improper mantanence

Quotef 20 for cleaning

Autor and inistalling new Tot

form.htm in Lar Bult Lock Mod. program.

12/12/2002

FLS 2/17/03