

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-20041

INITIAL CUSTOMER ORDER NO.

FPS

DATE RECEIVED
09/23/92DATE OPENED
10/02/92DATE CODE
CL 4-91SERIAL NUMBER
7675320

NEW SERIAL NUMBER

MODEL AND GRADE
7 308 WINACCESSORIES
W/STUDS

FROM:

SHIP TO:

BBJ'S
448 HWY 46
DICKSON

TN 37055

BBJ'S
448 HWY 46
DICKSONTN
37055

CUST NO: 058517 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE



CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

10/9/92

UPS

GUN CONDITION

- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

MAIN FAULT

Disassembly of rifle revealed dirt and rust on bottom of barrel, receiver and on and in trigger assembly. Rust inside of trigger assembly is causing internal trigger parts to bind and not move freely. Receiver, bolt would not cock - rifle was inoperative.

Top receiver became wet and dirty during use and was not cleaned after. Unproper maintenance.

ARTS

COMMENTS

Charge to clean rifle and replace trigger assembly.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

PS01282