

COMMENTS

CUSTOMER ORDER NO.	
--------------------	--

RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
1/25/94	03/26/94	WU 8-71	6468752		700 30-06 BDL
SSORIES	SLING STRAP	W/STUDS	W/SWIVELS	SCOPE BASE	

1: _____
[
COOPER, THOMAS E.
1700 1 WILLIAMS CTR.
TULSA
OK 74172

SHIP TO:
COOPER, THOMAS E.
1700 1 WILLIAMS CTR.
TULSA
74172

CUST NO: 097858 C.O.D L

UNIT NUMBER	ACCOUNT NUMBER N/C <i>059001</i>	WRITE ☐	PROM. DATE	ESTIMATED .	VIA UPS
-------------	-------------------------------------	--------------------------------	------------	----------------	------------

CONDITION	REPAIR CHARGE
EW	EXCISE
GHTLY WORN	TAX
ORN	INSURANCE
ERY WORN	UPS
NREPAIRABLE	PARCEL POST
BARRED	TOTAL

TOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
---------------	------	----------	--------	----------	-----	---------

E	A1	B1				
GER GROUP		B2			F1	F1
ASSY.		B3			E2	F2
REL ASSY.		B4		D1	E3	F3
ASSY.		B5		D2	E4	F4
ID			C1	D3	E5	F5
AL			C2			

FAULT Upon receipt, we were unable to duplicate customer's
problem. Trigger pull measured at 3.5-4 LBS. Gear lift .010.
Trigger adjusting screw and Trigger stop screw have been re-set
to factory as per last file missing. Minimum overhaul
replace Trigger assembly at r/c to customer at gesture
of good-will. See info 8-71. TN 5-26-94

[illegible]

OFFICE COPY

RD8925 REV. 1/94

PS01477