

RECEIVING AND ESTIMATING REPORT

CUST NO: 049349 C.O.D		COMMENTS	
CUSTOMER ORDER NO.			
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER
7/12/91	09/18/91	KW 5-72	6552407
MODEL AND GRADE		BDL	
700 270		ORDER	
R 91-18387			
ACCESSORIES		SCOPE BASE	
W/STUDS		W/SWIVELS	
		L/SIGHTS	

TO:	SHIP TO:
CLARK, JIM	CLARK, JIM
RT 2 BOX 111	RT 2 BOX 111
FREINDSHIP RD	FREINDSHIP RD
AMITE	AMITE
USA	USA
LA 70422	LA 70422

QUANTITY	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					10/29/91	UPS

IR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

IN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: "My Remington 700 went off when I chambered a round."

FAULT: Cannot make rifle malfunction in any way. However, trigger assembly has been adjusted outside factory - Trigger pull measures 2 lbs. 10 oz. Below our minimum specification. Safety is missing from all 3 adjustment screws. Seen left - 008"

Based on attached letter, customer would prefer a non-cock lock safety. As a gesture of good-will, offer a new style trigger assembly at $\pm$ normal cost.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
DE					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PS01591