

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00050087 Account # - R-	Description/Serial Number A6421673 Model 700 Center Fire Caliber: 3006 BDL	Date Received - 8/7/2002 Estimate Date - 8/5/2002 Current Date - 8/8/2002
Customer ALVIN DOWNS 130 HIGHCREST POINT BLANK, TX 77364 US Phone (H) (936)-377-3051 Phone (W)	Return To ALVIN DOWNS 130 HIGHCREST POINT BLANK, TX 77364 US	Fax Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FO
M992	GUN FIRED WHEN BOLT HANDLE LIFTED	M992	GUN FIRED WHEN BOLT HANDLE LIF

Technician's Comments	
ProblemNotes	could not duplicate altered adjustments and sticky residue clean action install new trigger under bolt lock modification QUOTE CUSTOMER \$ 20.00

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000118	GR-CLEAN	1	Y
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service Total:		23	


10 LBS 1 OF 1

REXINGTON ARMS CO INC
800 243-9700
14 HOEFER AVE
ILION NY 13357

SHIP

TO:

ALVIN DOWNS
130 HIGHCREST
POINT BLANK TX 77364




TX 773 0-02



UPS GROUND

TRACKING #: 1Z 114 813 03 1192 2104



BILLING: P/P

INV#: RE00050087

ASC 05.00 J69K/J64K 16.0A 01/201

PS01688