

Remington Arms Company, Inc.

Parts/Repairs 800-243-9700
Fax 336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number
RE00072136
Account # - R-

EREMO

Description/Serial Number
B6410392

Model 700 Center Fire Caliber: 308 ADL

Date Received - 10/30/2003
Estimate Date -
Current Date - 11/13/2003

Customer
GANDER MOUNTAIN COMPANY
ATTN CINDY KILBRIDE
P.O. BOX 1224
MINNEAPOLIS, MN 55440 US

Return To
GANDER MOUNTAIN
ATTN GUN PARTS DEPT
955 VIEWMONT DR
DICKSON CITY, PA 18519 US

Phone (H) (570)-347-9077
Phone (W)

Fax
Email

Reported		Problems		Found	
M990	TRIGGER NEEDS ADJUSTMENT	M123	FORWARD TO PRODUCT SERVICE FO		

Technician's Comments	
ProblemNotes	Trigger assembly components rusty. Poor maintenance. Replace trigger assembly at no charge. D.S.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000119	GR-TEST	1	Y
Service Total:		1	