

"Gun fires when bolt shuts"
Concern -

Could not duplicate

TA coated with sticky
residue - sear can barely
move, Trigger slow regaining,
bolt release sticks.


Install new TA at $\frac{1}{2}$ normal
charges.

FLS 6/4/01

Serial
Number:

6750980

Model: 700



RE00028100

EUBANK'S WESTERN CORNER

122 S. Main

Lindsay, OK 73052

EUBANK'S WESTERN CO

122 S. Main

Lindsay, OK 73052

28100

