

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs 800-243-9700
Fax 336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00045931 Account # - R-	Description/Serial Number 170177 Model 722 Center Fire Caliber: 223	Date Received - 5/8/2002 Estimate Date - 5/6/2002 Current Date - 5/9/2002
Customer SHOOTERS SUPPLY INC 1120 TIETON DRIVE YAKIMA, WA 98902 US Phone (H) (509)-452-1181 Phone (W)	Return To SHOOTERS SUPPLY INC 1120 TIETON DRIVE YAKIMA, WA 98902 US Fax Email	

Problems			
Reported		Found	
M239	REPLACE TRIGGER ASSEMBLY	M123	FORWARD TO PRODUCT SERVICE FO
M992	FIRED WHEN PUT ON SAFE	M238	CLEAN & INSPECT
		M239	REPLACE TRIGGER ASSEMBLY

Technician's Comments	
ProblemNotes	Bolt Lock Modification Program. Quote customer \$20.00 for new trigger assembly and clean action. FLS 5/2/02. NOTE - Caliber altered outside of factory, bench test only.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part	Total:	1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000118	GR-CLEAN	1	Y
Service	Total:	21	


10 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 HOEFER AVE
ILION NY 13357

SHIP

TO:

SHOOTERS SUPPLY INC
1120 TIETON DR
YAKIMA WA 98902-3836




WA 989 0-00



UPS GROUND

TRACKING #: 1Z 114 813 03 1188 1702



BILLING: PREPAID

INV#: RE00045931

ASC 3.70 J69X/J64X 14.0 01/200