Remington.

TRACKING DOCUMENT

Repair Order Number

Repair Order Number

RE00081239

Description/Serial Number

F6242415

Account # - R-

Model 700 Center Fire VAR LAM

Repairman -

Carl Cotton

Date Received · 6/1/2004

Estimate Date -

Current Date - 6/2/2004

Customer

FIN FEATHER FUR OUTFITTERS INC

652 US 250 EAST

ASHLAND. OH 44805 US

Return To

FIN FEATHER FUR OUTFITTERS INC

652 US 250 EAST

ASHLAND. OH 44805 US

Phone (H) Phone (W) (419)-281-2557

Fax

(419)-281-0787

Email

Problems Reported M106 COULD NOT DUPLICATE CUSTOMEI M992 FIRES WHEN BOLT IS CLOSED M178 TRIG ADJ SCREWS RESET, CANNOT

<u>Material #</u>	MaterialDesc Repair.	<u>Quantity</u> <u>Needed</u>	<u>Quantity</u> <u>From Inv</u>	Quantity From Kit	<u>Warranty</u> (Y/N)
Part	•				
F26345	700 TRIG ASSB RH	1	1	0	\mathbf{Y}
Part	Total:	1	1	0	
Service					
4000294	GR-CHECK TPA	1	1	0	Y
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000119	GR-TEST	1	1	0	Y
Service	Total:	2	2	0	

ProblemNotes Replacing trigger assy. at n/c, strictly as a gesture of good-will.

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date