

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORD
R 95-291

INITIAL CUSTOMER ORDER NO.

JJM

ATTN JACK KAST

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/20/95

11/22/95

DX 9-73

A6927453

760 270

ADL

ACCESSORIES

FROM:

GEIBEL, RALPH
208 NORTH DR
BUTLER

PA 16001

SHIP TO:

GEIBEL, RALPH
208 NORTH DR
BUTLER

PA

16001

CUST NO:131809 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☒ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

250.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

SLT ASSY.

B3

BARREL ASSY.

B4

EC. ASSY.

B5

WOOD

C1

METAL

C2

VIN FAULT

Mfgn. 9/73 Damage to gun resulted from firing a shell that developed extreme high pressure. The locking lugs in the barrel extension are completely sheared off indicating gun was locked up and operating properly at the time of the incident. Remington Arms Co. cannot be responsible for a condition beyond our control. Exchange gun at a special price strictly on a gesture of good will.

ARTS

COMMENTS

M/760 270

No incident case head or body returned, appears that case body was removed from chamber. Breech bolt missing

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PS02761