## Remington.

## TRACKING DOCUMENT

## Repair Order Number



Repair Order Number

RE00091894 Account # - R- Description/Serial Number

ML028219

Model 700ML Center Fire Caliber: 50

SYN

Repairman -

Robert Frink Date Received - 1/29/2005

Estimate Date -

Current Date - 2/1/2005

Customer

JAMES E GATTON 1607 180TH STREET

LUVERNE, IA 50560 US

Return To

JAMES E GATTON 1607 180TH STREET

LUVERNE, IA 50560 US

Phone (H) Phone (W) (515)-295-3921

Fax Email

Problems Reported M123 FORWARD TO PRODUCT SERVICE M123 FORWARD TO PRODUCT SERVICE F FOR INSPECTION M992 WON'T ALWAYS COCK WHEN BOLT IS CLOSED M993 **DISCHARGES WITHOUT PULLING** 

<u>Material #</u>	<u>MaterialDesc</u>		<u>Ouantity</u> Needed	<u>Quantity</u> From Inv	<u>Quantity</u> From Kit	<u>Warranty</u> (Y/N)
Part F99294	700 ML SS TRIG ASSB	i .	. 1	1	0	Y
Part	Total:	:	1	1	0	
Service 4000104 Service	ARMS SERV SHIPPING & HANDLING Total:		0	<u>0</u>	0	Y

Condition Firing pin and nipple not of our manufacture. ProblemNotes

Searcam damaged. Replace trigger assembly and check over completely at no charge.

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date