

Excessive Lubr On
Assy. (WD-40) Tris Pull
Adjusted Outside Of
Factory Appears To Have
(over)

REPAIRMAN	PROOF	CLEAN	TR
GALLERY TESTER	DATE	DATE	DR

PS02933