

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-17862

INITIAL

CUSTOMER ORDER NO.

FJB

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

08/26/92

09/04/92

DU 9-71

6478324

700 270

ADL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

HURLEY, LARRY
PO BOX 932
CLINTON

TN 37717

SHIP TO:

HURLEY, LARRY
PO BOX 932
CLINTON

TN

37717

CUST NO: 065954 C.O.D.L.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

MAIN FAULT

Cannot duplicate either of these complaints after many attempts. However, it was noted that rust is present on the bottom side of the trigger and on the connector. Also, the trigger operation is somewhat slow, possibly because of this rusted condition.

Trigger pull 3 1/2 pounds; ear lift 1013"

ARTS

- 1) File
2) Copy to Suppy

COMMENTS

Since trigger assembly is rusted from unknown cause, trigger and connector became the edge of the rifle. Offer new trigger assembly at a nominal cost, as a gesture of goodwill.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/92

PS03008