

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-05273

INITIALS CUSTOMER ORDER NO.

JJM 006749

STEKL

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

02/10/92

02/14/92

AV 3-79

A6733138

700

30-06

ADL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM

SHIP TO:

HOPKINS, HARRY E
RR 1 BOX 349
FALLS
UPS

PA 18615

HOPKINS, HARRY E
RR 1 BOX 349
FALLS
UPSPA
18615

CUST NO: 058196 C-10-D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

3/5/92

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Cannot duplicate above complaint. Trigger and safety assembly operate normally. However, it was noted that the assembly has been adjusted improperly outside the factory. Trigger pull 2 1/2 pounds (below our minimum specification 2) Overtravel is excessive. It was also noted trigger assembly was extremely oily. Seal left "oil"

PARTS

COMMENTS

Offer to clean and re-adjust present trigger assembly (if possible) or we can offer a new trigger assembly at a nominal cost, also a coupon of good-will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTER

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 6

PS03020