

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-24094

INITIAL CUSTOMER ORDER NO.

LJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/06/92

11/10/92

6333729

700

25-06

BDL

ACCESSORIES

SCOPE BASE

L/SIGHTS

L/STUDS

KT 5-70 2ND TIME IN

FROM:

SHIP TO:

HONEYCUTT, B M
RT 1 BOX 681
FLOYD

VA 24091

HONEYCUTT, B M
RT 1 BOX 681
FLOYDVA
24091

CUST NO:069882 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

11-25-92

UPS

IN CONDITION

NEW

LIGHTLY WORN

WORN

VERY WORN

UNREPAIRABLE

MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

/CLE

A1

B1

TRIGGER GROUP

B2

SLT ASSY.

BARREL ASSY.

E.C. ASSY.

COD

ETAL

IN FAULT

Cannot duplicate complaint. Rifle & trigger assembly operate normally. Trigger assembly has been altered outside factory - trigger pull is 24 pounds, this is well below our minimum spec. Trigger pull 24 pounds; rear lift .008"

ITS

COMMENTS

Offer following options:

- 1) to re-adjust present trigger assembly to factory spec
- 2) to install new trigger assembly at \$ normal cost, as gesture of good-will, if that will better restore confidence in the rifle.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/92

PS03025