

ORDER
R 91-25248

_____ DH 9-87 2ND TIME IN

SHIP TO:

TX
75670

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	TARP	PROM. DATE	ESTIMATED	VIA
						UPS

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	S1				
TRIGGER GROUP		S2				F1
BOLT ASSY.		S3				F2
BARREL ASSY.		S4				F3
REC. ASSY.		S5				F4
WOOD			C	D	E	F5
METAL						

MAIN FAULT	COMMENTS
Unable to duplicate complaint. However, trigger assembly has been grossly mis-adjusted out of factory. 1) rear-excessiveness extremely, excessive 2) excessive over 1/2 inch 3) trigger pull heavy at 6 1/2 pounds. Sealant mixing from all adjustment screws. Bolt stop gummed up, not working properly. Also, trigger assembly has excessive grease (?) outside of handle. Owner should not alter trigger assembly adjustments!!	Sealant - 100% All

COMMENTS Offer replacement trigger assembly
at 1/2 normal cost, as gesture of goodwill

[illegible]