

Date: 11/30/2004

By: FRED SUPRY

**FIREARM INSPECTION WORKSHEET**

**BACKGROUND**

Customer name: Art Hamlin

R.E. Number: 88107

Reason for inspection: FIRED ON SAFE RELEASE

**FIREARM**

Manufacturer: REM Model: 700

Serial Number: 6553935 Date of Manufacture: 5/2/1972

Overall external condition: FAIR

Barrel condition: ok

Receiver condition: ok

Stock condition: ok

Bolt/firing pin condition: ok

Trigger assembly condition:

Engagement: Altered

Adjustments/alterations: Altered

Other: Sticky residue

Headspace: \_\_\_\_\_

Function evaluation:

Feeding: \_\_\_\_\_

Extraction/ejection: \_\_\_\_\_

Trigger pull: \_\_\_\_\_

Manual safety: ok

Test firing results (if applicable): \_\_\_\_\_

DISPOSITION

Clean Action and install new TA at  
~~the~~ normal charges for Bolt lock modification.

ADDITIONAL COMMENTS

Trigger would not reliably return under  
Sear, due to altered adjustments.