

RECEIVING AND ESTIMATING REPORT ✓

INITIAL		CUSTOMER ORDER NO.		COMMENTS W/LEUPOLD 3X9 SCOPE			
PS							
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER	
4/22/91	04/24/91	PR 6-68	356899	700	30-06	HDL	R 91-0966
ACCESSORIES		HARD CASE		SCOPE MNTS		SCOPE BASE	
W/STUDS		L/REAR SIGHT					

FROM: KING, DAVID J
BOX 594
KODIAK AK 99615

SHIP TO: KING, DAVID J
BOX 594
KODIAK AK 99615

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA ☒ UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	---

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	-----	-----------	-----	-------------	-------

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☒ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: "...at long fire sometimes, and other it fails to fire. After I pull the trigger, it will fire on a delayed period of time."

MAIN FAULT: Trigger assembly is contaminated with an oily, gunning residue. As a result, the rear sight cam is sticking to the trigger assembly side plate. Rifle operates normally at room temperature, however, cold temperature could cause the described problem.

RTS: Clean present trigger assembly if possible, if not, send replacement trigger assembly at 1/2 normal cost, as a gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD4925 REV. 7/90

PS03497