

Part
Number:

E6278606

Model: 700



RE00044030

Trigger will not return
under seal properly,
Altered adjustment, and
Sticky residue.

BOB TOMES 
McKinney/Allen's Friendly Ford Dealer

Charles Kovacs
2562 Honeysuckle
Richardson, TX.
75082

Clean action, & Bolt Assembly
Install new TA, Test.

at w/c

Charge 230145

FCS 3/27/02