

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-05705

INITIAL CUSTOMER ORDER NO.

JJM

BOTTOM HALF OF SEE THRU MTS ONLY

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

02/14/92

02/20/92

DR 9-68

366825

700 308

BDL

ACCESSORIES

W/STUDS

FROM

SHIP TO:

KERSCHNER, BRAD J
205 JEFFERSON ST
SCHUYLKILL HAVEN

PA 17972

KERSCHNER, BRAD J
205 JEFFERSON ST
SCHUYLKILL HAVEN PA
17972

CUST NO: 058422 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5			E4	F4
WOOD		C1		D3	E5	F5
METAL		C2				

MAIN FAULT

It is not possible for a Model 700 rifle to fire when the bolt is being moved forward after opening, due to the design.
Examination of the fully assembled trigger assembly could not produce a malfunction of any kind. However, disassembly of the rifle revealed the trigger assembly has been improperly adjusted in the following - 1) trigger pull was measured to be 2.5 lbs (below our minimum spec) 2) over-travel excessive. Nevertheless, the rifle did not malfunction.

PARTS

COMMENTS

Offer to clean and re-set present trigger assembly, or, we can install a new trigger assembly at a normal cost, as a gesture of good will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 8/91

PS03752