

Repair Order Number



Repair Order Number RE00050981	Description/Serial Number 6342035	Repairman - Robert Frink Date Received - 8/29/2002
Account # - R-	Model 700 Center Fire Caliber: 3006 ADL	Estimate Date - 8/22/2002 Current Date - 9/4/2002
Customer ALBERT LUIZ 1924 LAKESHORE ROCKWALL, TX 75087 US	Return To ALBERT LUIZ 1924 LAKESHORE ROCKWALL, TX 75087 US	
Phone (H) (972)-494-7109 Phone (W)	Fax	Email ALUIZ@HAT-CO.COM

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F

Material #		MaterialDesc		Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part							
F26345		700 TRIG ASSB RH		1	1	0	Y
Part Total:				1	1	0	
Service							
4000104		ARMS SERV SHIPPING & HANDLING		0	0	0	Y
4000116		GR-LABOR		20	20	0	N
4000118		GR-CLEAN		1	1	0	Y
4000119		GR-TEST		1	1	0	Y
Service Total:				22	22	0	

Condition	REC'D W/ OILED STK FINISH.				
ProblemNotes	Action and trigger assembly dirty. Trigger adjustment and stop screws altered. Replace trigger assembly \$20.00. D.S.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date


14 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 HOEFER AVE
MILTON NY 13357

SHIP

TO:

ALBERT LUIZ
1924 LAKESHORE
ROCKWALL TX 75087




TX 751 9-04



UPS GROUND

TRACKING #: 1Z 114 813 03 1193\6788



BILLING: P/P

INV#: RE00050981

ASC 05.00 J69X/J64X 16.0A 01/2002