

RECEIVING AND ESTIMATING REPORT

COMMENTS

to Product Service

ORDER
R 93-26496

INITIAL CUSTOMER ORDER NO.

PS

DATE RECEIVED 1/30/93	DATE OPENED 12/09/93	DATE CODE AY 3-74	SERIAL NUMBER 6724393	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06	ADL
--------------------------	-------------------------	----------------------	--------------------------	-------------------	------------------------------	-----

ACCESSORIES W/STUDS

FROM:

SHIP TO:

LOVE, JERRY
1321 9TH WEST
KEMMERER

WY 83101

LOVE, JERRY
1321 9TH WEST
KEMMERER

WY
83101

CUST NO: 088284 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	------------

- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	25.00
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

*UPS
COD*

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
RIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

*Upon receipt, unable to duplicate Customer Concern.
Examination revealed that the action and trigger assembly are bound
with dirt, rust, and a heavy sticky substance. Bolt stop release
will not retract. Rifle had good cleaning. Mfg 1974*

ARTS

COMMENTS

*Replace compressed trigger
assembly and clean action at
1/2 normal replacement cost*

REPAIRMAN <i>MF</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

Go ahead