

Serial
Number:

A6472789

Model: 700



RE00021860

Internal mechanism
sticky - outside of TA
Recently cleaned - inside
TA so gummy the trigger,
bolt release barely move.

MELVIN L. MANZER

MASONRY

BOX 335 - South Gibson, Pa. 18842

Phone 717-222-4437

Date 1/23/01

Install new TA at

1/2 normal charges

FCS 2/2/01

Remington Arms Co.

14 Hooper Ave Union Ny Ny 13357

Sir,

In reference to speaking to you
on the telephone. I was watching CNN
news about your 700 Rem about the
trigger & safe. I had the same
experience as they did. Luckily no
injuries. I thought it was the
bolt & had a gun smith check it
but it was alright. So I would like
you to check it out & fix it please.
I would like my trigger pull set
at 4.5# pull.

Thanks.

M. L. Manzer

21860