

RECEIVING AND ESTIMATING REPORT

Service Dept

IN BDL/MAG R ORDER 90-30845

1. Check barrel see if it will group
2. safety need to be changed goes off when open bolt
3. put in extractor cos bolt its getting old

SHIP TO:

MEDENWOLD, KM
RR 1
HANKINSON

ND
58041

ST

PROM. DATE

ESTIMATED

VIA

12-17-90

V456729574

UPS

PARCEL POST

TOTAL

VERY WORN

☐ MISUSED

☐ MARRED

KM Medenwold
RRI
Hankinson N. Dak

701-242-7934
Easy to take, easy to tolerate.

PCE

erythromycin particles in tablets

Abbott Laboratories North Chicago, Illinois 60064

be changed Goes off
check BBI see if it

tigger assembly and safety function
has been improperly adjusted
and the wti of pull and
not removed and not replaced.

dry test up for accuracy

you to either properly re-adjust the
ent tigger assembly or, offer to
replace tigger assembly at 1/2 normal
price as a gesture of good-will, if it
will better restore confidence in the
up.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
R32					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PS04349