

RECEIVING AND ESTIMATING REPORT

COMMENTS

ATTN: J. STEKL

CUSTOMER ORDER NO.

RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
06/90	09/18/90	RZ 11-75	A6208763	600 243 MOHAWK	R 90-24056
DRIES SLING STRAP W/STUDS W/SWIVELS SCOPE BASE L/SIGHTS W/ RECOIL PAD					

SHIP TO:

PRIDGEN, LYNN
RT 6
BOX 6366
PALESTINE TX 75801

MAIL & MORE
712 W OAK ST

PALESTINE

TX
75801

ITEM NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	FROM, DATE	ESTIMATED	VIA
					UPS

CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
--------	-----	-----------	-----	-------------	-------

CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☒ VERY WORN ☐ MISUSED ☒ MARRED

REPAIR REQUEST

... it discharged when I took it off safety...

*Could not duplicate complaint, however, disassembly revealed
safety has been removed from all 3 trigger adjusting screws and
screws have been affected outside of factory - 1) no trigger adjustment
4) 1) trigger over travel 2) excessive engagement*

*either re-adjust trigger assembly to
proper specification or if that is not
possible, send quotation for & would
prior to replace trigger assembly.*

*7/21/90
JMS.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6923 REV. 6/88