

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-13438INITIAL
FPS

CUSTOMER ORDER NO.

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

ACCESSORIES

W/STUDS

SCOPE BASE

L/REAR SIGHT

FROM:

PENN, RON
1111 ROUTE 6N
WATERFORD

PA 16441

SHIP TO:

PENN, RON
1111 ROUTE 6N
WATERFORDPA
16441

CUST NO: 896164 CLO.D

ACCOUNT NUMBER

ACCOUNT NUMBER NC

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Upon receipt could not operate. However, examination reveals
 a thick black, greasy substance inside the trigger housing and on both sides
 of the sear spring. This substance was removed and the trigger housing and
 sear spring were cleaned. The trigger housing and sear spring were then
 reassembled and the trigger was tested. The trigger now operates
 properly.

PARTS

COMMENTS

25345 Trigger Housing
 92458

Trigger pull measured 3 1/2 to 3 3/4
 lbs all stock. Some light wear. 014

Positive complete trigger assembly
 and clear action at 1/2 normal speed
 and, as given at 1/2 speed.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94