

RECEIVING AND ESTIMATING REPORT

COMMENTS

L/ SIGHTS W/ WILLIAMS SIGHTS

INITIAL CUSTOMER ORDER NO.

FJB

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

MODEL AND GRADE

ORDER

10/29/90

10/31/90

EN 10-66

243174

700

30-06

ADL

R

90-28545

ACCESSORIES

FROM:

PUVEL, ROBERT H.
35 CLARK DR
BRADFORD PA 16701

SHIP TO:

PUVEL, ROBERT H.
35 CLARK DR
BRADFORD PA 16701

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM DATE

ESTIMATED

VIA

V429843041

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☒ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

"...I pushed the safe to the fire position to empty the gun at that time it fired."

MAIN FAULT

Trigger assembly has been completely misadjusted out of factory (Bedant firing pin all 3 adjustment screws) No striation spring force at all — as received, firing pin would not rock — too little bear engagement coupled with no trigger attraction.

PARTS

Owner claims gun is just over 2 years old, however, it was produced on October 27 1966.

Send repair quotation for new trigger assembly.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE