

TO WHOM IT MAY CONCERN:

THE ENCLOSED REMINGTON MODEL 721
30/06 HAS TWICE DISCHARGED DURING
UNLOADING WHEN THE BOLT HANDLE WAS
PUSHED DOWN INTO THE LOCKED POSITION.
IN NEITHER CASE WAS THERE ANY POSSIBILITY
THAT ANYTHING WAS IN CONTACT WITH
THE TRIGGER.

PLEASE REPAIR AND RETURN TO:

CHARLES R. STRAIN
716 GREEN FOREST RD
RIDGELAND, MS
39157

TEL. NO. (601) 956-8929

THANKS,

Charles R. Strain