

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R93-10747

INITIAL C-STOP ORDER NO.

ATTN: DENNIS SANITA
W/BTM PART OF SCOPE MNTS

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
1/26/93	04/27/93	CQ 4-78	A6391981		700 25-06 BDL
ACCESSORIES	W/STUDS	SCOPE BASE			

L/REAR SIGHT

OM:

SHIP TO:

STANLEY, DAVID
112 TEXAS AVE
P O BOX 427
HEWITT

TX 76643

STANLEY, DAVID
112 TEXAS AVE
P O BOX 427
HEWITTTX
76643

CUST NO: 078557 C.O.D

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
					UPS
CONDITION					REPAIR CHARGE
NEW					EXCISE 25.00
LIGHTLY WORN					TAX
WORN					INSURANCE
VERY WORN					UPS
UNREPAIRABLE					PARCEL POST
DAMAGED					TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
LE	A1	B1				
GER GROUP		B2			E1	F1
ASSY.		B3			E2	F2
REL ASSY.		B4		D1	E3	F3
ASSY.		B5		D2	E4	F4
D			C1	D3	E5	F5
L			C2			

Unable to duplicate Customer Concern. However, examination revealed heavy gummy, sticky substance on bolt stop, trigger, action, and trigger housing. Adjustment and the trigger stop were found to have been in normal position. Perhaps, indicating adjustment screws have been tampered with.

upper bolt 4 1/2 lb.
in left .008

COMMENTS

Replace complete trigger assembly
and manufacture at 1/2 normal
replacement cost, as given up good
unit.

Gr. Shend

DEFECTS	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PS05479