

RECEIVING AND ESTIMATING REPORT

COMMENTS

ARTHUR DENNIS SANETA

INITIAL RLP	CUSTOMER ORDER NO.					
DATE RECEIVED 02/26/90	DATE OPENED 03/01/90	DATE CODE WU 10-71	SERIAL NUMBER 6486174	MODEL AND GRADE 700 30-6 BDL		ORDER R 90-00204
ACCESSORIES W/STUDS		SCOPE BASE				

FROM:

LARRY SCHENEWERK
615 TERRACE DR
CALIFORNIA MO 65018

SHIP TO:

LARRY SCHENEWERK
615 TERRACE DR
CALIFORNIA MO 65018

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	-------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐

NEW

☒

SLIGHTLY WORN

☐

VERY WORN

☐

MISUSED

☐

MARRED

CUSTOMER'S REQUEST

accidental firings

MAIN FAULT

Trigger assembly & felt stop completely contaminated with some sticky substance. Bolt will sometimes not cock, firing pin follows down on cocking cam.

PARTS

1) Per customer's request during phone conversation 3/6/90 - replace trigger assembly with new-style safety - no-bolt lock, at N/C

2) Charge \$10.00 handling plus return postage.

3) Send new Owner's Manual with rifle when returned.

3/6/90 JAL

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6/88

PS05510